L Number	Hits	Search Text	DB	Time stamp
10	10919		USPAT	2004/09/02 19:06
11	3908		USPAT	2004/09/02 19:06
12	2075798		USPAT	2004/09/02 19:07
13	2100397		USPAT	2004/09/02 19:03
14	378		USPAT	2004/09/02 19:07
15	33		USPAT	2004/09/02 19:03
16	1074			2004/09/02 19:04
17	4347		USOCR	2004/09/02 19:07
18	1135325		USOCR USOCR	2004/09/02 19:07
19	525		USOCR	2004/09/02 19:07
21	0		USOCR	2004/09/02 19:07
22	3915	FCC	US-PGPUB;	2004/09/02 19:07
			EPO; JPO	2004/09/02 19:07
23	514	standpipe	US-PGPUB;	2004/00/02 10:07
			EPO; JPO	2004/09/02 19:07
24	725661	withdrawal well	US-PGPUB;	2004/09/02 10:07
			EPO; JPO	2004/09/02 19:07
25	40	standpipe with (withdrawal well)	US-PGPUB;	2004/00/02 10-07
		Tapa was (Masharanar World)	EPO; JPO	2004/09/02 19:07
26	2	FCC and (standpipe with (withdrawal well))	US-PGPUB;	2004/00/03 10-00
	_	(EPO; JPO	2004/09/02 19:08
-	1	("6228328").PN.	USPAT	2002/10/20 15 00
	16	("2530243" "2581134" "2741546"	USPAT	2003/10/30 16:02
		"2769771" "2893851" "2944009"	USPAI	2003/10/30 16:00
		"3031769" "3099538" "3394076"	1	
		"3607730" "3775302" "4329526"	1	ĺ
		"4511434" "5529587" "5562818"		
		"5779746").PN.		
_	10139	FCC	TIOD N III	0000/10/00
-	3752	standpipe	USPAT	2003/10/30 16:02
1 - 1	683325	openings slots slits inlets	USPAT	2003/10/30 16:02
_	239	standpipe with (openings slots slits	USPAT	2003/10/30 16:14
	203	inlets)	USPAT	2003/10/30 16:03
_	7	FCC and (standpipe with (openings slots	HODAM	2222/12/22
		slits inlets))	USPAT	2003/10/30 16:05
-	76515	cracking	HODAM	0000/40/00
-	16	cracking and (standpipe with (openings	USPAT	2003/10/30 16:05
		slots slits inlets))	USPAT	2003/10/30 16:05
_	9	(cracking and (standpipe with (openings	HCDam	0000/10/10
	_	slots slits inlets))) not (FCC and	USPAT	2003/10/30 16:05
		(standpipe with (openings slots slits		
	ĺ	inlets)))		
-	60724	outlets	tic Dam	2002/12/20 45 45
-	42	standpipe with outlets	USPAT	2003/10/30 16:11
-	8	(standpipe with outlets) and (FCC or	USPAT	2003/10/30 16:11
		cracking)	USPAT	2003/10/30 16:14
_	10	("2654659" "2816011" "2881130"	חעמטוו	2002/10/22 75 75
		"2881133" "3016624" "3092468"	USPAT	2003/10/30 16:13
ļ		"3215508" "4051013" "4101288"		
		"4226830").PN.		
-	17389	riser	HGDVW	2002/10/22 ===================================
-	706087	openings slots slits inlets outlets	USPAT	2003/10/30 16:14
-	1433	riser with (openings slots slits inlets	USPAT	2003/10/30 16:14
		outlets)	USPAT	2003/10/30 16:14
-	267	(riser with (openings slots slits inlets	IICDAM	2002/10/22
		outlets)) and (FCC or cracking)	USPAT	2003/10/30 16:17
-	8595	regenerator	IICDAM	2002/10/22
-	183	((riser with (openings slots slits inlets	USPAT	2003/10/30 16:17
		outlets)) and (FCC or cracking)) and	USPAT	2003/10/30 16:17
		regenerator		İ
-	1	("3394076").PN.	HCDAM	0000/10/05
-	27	("2398739" "2414002" "2416730"	USPAT	2003/10/30 16:30
	- '	"2434567" "2459474" "3041273"	USPAT	2003/10/30 16:35
		"3152065" "3785959" "3835023"		1
		"3849291" "3990992" "4026789"	į	
1		"4176084" "4200520" "4239654"		
		"4242237" "4289606" "4331533"		
İ		"4332673" "4332674" "4336160"	ĺ	
		"4349156" "4354923" "4405445"		
		"4407714" "4427537" "4434049").PN.		ļ
		, 1434049).PN.		

	17	"0197486"	T	
_	17	"019/480"	EPO;	2003/11/25 13:59
		W0107406W	DERWENT	
-	0		EPO	2003/11/25 13:58
-	0	"197486"	EPO	2003/11/25 13:58
-	0	"catalyst regeneration process and	EPO;	2003/11/25 13:59
		apparatus"	DERWENT	1
_	0	"ep-0197486-A1"	EPO;	2003/11/25 14:02
			DERWENT	
-	1	("3394076").PN.	USPAT	2003/11/25 14:11
-	11	3394076.URPN.	USPAT	2003/11/25 14:02
-	1575850	1 Proming openings bare bares	USPAT	2003/11/25 14:12
	İ	hole holes		
_	75864	slotted	USPAT	2003/11/25 14:12
-	2191072	plurality several multiple	USPAT	2003/11/25 14:12
-	218161	(slot slots opening openings slit slits	USPAT	2003/11/25 14:12
		hole holes) near3 (plurality several		2000/11/20 11:19
		multiple)		
_	260520	standpipe pipe	USPAT	2003/11/25 14:13
-	5458	(slotted or ((slot slots opening openings	USPAT	2003/11/25 14:13
		slit slits hole holes) near3 (plurality	332111	2003/11/23 14:13
		several multiple))) with (standpipe pipe)	}	
 -	57830	FCC regenerator regeneration	USPAT	2003/11/25 14:14
-	131	((slotted or ((slot slots opening openings	USPAT	2003/11/25 14:14
		slit slits hole holes) near3 (plurality		2003/11/23 14.14
		several multiple))) with (standpipe pipe))		İ
		and (FCC regenerator regeneration)		
-	233707	catalyst	USPAT	2003/11/25 14:14
-	2681	(standpipe pipe) near5 catalyst	USPAT	2003/11/25 14:14 2003/11/25 14:14
-	37	(((slotted or ((slot slots opening	USPAT	2003/11/25 14:14 2003/11/25 14:14
	i	openings slit slits hole holes) near3	552111	2003/11/23 14:14
		(plurality several multiple))) with		
	İ	(standpipe pipe)) and (FCC regenerator		
		regeneration)) and ((standpipe pipe) near5	-	1
		catalyst)		
-	14	("2344770" "2391327" "3161583"	USPAT	2002/11/25 14 17
		"3206393" "3316170" "4217243"	USPAI	2003/11/25 14:17
		"4217244" "4243517" "4243518"		
		"4354957" "4374021" "4440725"		
		"4849091" "4965232").PN.		
	8	("3494858" "3661800" "3886060"	USPAT	2002/11/05 14 21
	Ĭ	"3893812" "3898050" "3909392"	USPAT	2003/11/25 14:21
	["3926778" "3926843").PN.		
-	19	3494858.URPN.	HCDAM	2002/11/05 1: 5=
L		0.5.000.0KLW,	USPAT	2003/11/25 14:25